

ARRIVAL ROUTE DESCRIPTION

KFLL: From TEEKY on track 136° to cross BANTY between 10000 and 11000 and at 250K, then on track 106° to cross HEEZE at 7000.

LANDING KFLL RUNWAY 10L: From HEEZE on track 105° to cross HOLID at 5000. Expect ILS or LOC Rwy 10L approach.

LANDING KFLL RUNWAY 10R: From HEEZE on track 107° to cross BUNKR at 5000. Expect ILS or LOC Rwy 10R approach.

LANDING KFLL RUNWAYS 28L/R: From HEEZE on track 096° to cross GOYLE at 7000, then on track 089° to cross BEPAC at 6000, then on track 092° to cross FAMBA at 6000, then on track 092°. Expect RADAR vectors to final approach course.

LANDING KFXE/KPMP: From TEEKY on track 136° to cross BACIN at 8000, then on track 104° to cross CANUR at 7000, then on heading 093° or as assigned by ATC. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS:

KFLL LANDING EAST RUNWAY 10R: Continue track to BUNKR, conduct ILS or LOC Rwy 10R approach.

KFLL LANDING EAST RUNWAY 10L: Continue track to HOLID, conduct ILS or LOC Rwy 10L approach.

KFLL LANDING WEST: Continue track to FAMBA, then proceed direct FUZZY, conduct ILS or LOC Rwy 28R approach.